## PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between the Seller and any Buyer. The Seller authorizes the Listing Broker in this transaction to disclose the information in this statement to other real estate licensees and to prospective buyers of this property. The Seller agrees to notify the Listing Broker promptly of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

## NOTE: DO NOT LEAVE ANY QUESTIONS BLANK. WRITE N/A (NOT APPLICABLE) OR UNKNOWN IF NEEDED. Cumberland Flats (Units 1-6)

PROPERTY LOCATED AT: Portland, ME

|   |  | SECTION I. WA   | ATER SUPPLY                                  |                                |  |  |
|---|--|---|--|--------------------------------|--|--|
| TYPE OF SYSTE   | M: <b>X</b> Public   | Private   | Seasonal NA                                  | Unknown                        |  |  |
|   | Drilled  | Dug   | Other NA                                     |                                |  |  |
| MALFUNCTION   |  |   | ctions with the (public/private/other) water | system?                        |  |  |
|   | Pump: Yes No   | X N/A   | Quantity:                                    |                                |  |  |
|   | Quality: Yes No  | X Unknown   |  |                                |  |  |
|   | (  |   | section below or with attachment.            |                                |  |  |
| WATER TEST:   |  | •   |  | Vac V No                       |  |  |
| WATER IEST.   | Have you had the water tested? Yes X No  IF YES: Date of most recent test: NA Are test results available? Yes X No |   |  |                                |  |  |
|   |  | To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes X No |  |                                |  |  |
|   | 2  |   |  |                                |  |  |
|   | IF YES, are test results available?  |   |  |                                |  |  |
| - IE DDIVATE.   | what steps were taken to re  | inedy the problem: 14A  |  |                                |  |  |
| • IF PRIVATE:   | LATION: Location: NA   |   |  |                                |  |  |
| INSTAL  | Installed BY: NA   |   | -DATE of Installation: NA                    |                                |  |  |
| LICE.   |  | in a secondario D.N.A   | DATE OF Instanation. NA                      |                                |  |  |
| <del>USE:</del>   | Number of Persons currentl   |   | 9  | V. D.N. D.Halas                |  |  |
| COMMENTS, No  |  | or more than one nousehold  | ?  | Yes No Unknown                 |  |  |
| COMMENTS: No  | ON I information: <b>Seller</b>  |   |  |                                |  |  |
| Source of SECTIC  |  |   | WATER DICEOCAL                               |                                |  |  |
|   | SE   | CHON II. WASIE  | WATER DISPOSAL                               |                                |  |  |
| TYPE OF SYSTE   | M: X Public Priv   | ate Quasi-Public <b>NA</b>  |  | Unknown                        |  |  |
| • IF PUBLIC OR  | QUASI-PUBLIC:  |   |  |                                |  |  |
| Have yo   | u had the sewer line inspected   | 1? Yes X No If yes  | s, what results: <b>NA</b>                   |                                |  |  |
| Have yo   | u experienced any problems s   | such as line or other malfund   | etions?                                      | Yes <b>X</b> No                |  |  |
|   | eps were taken to remedy the   |   |  |                                |  |  |
| • IF PRIVATE:   |  |   |  |                                |  |  |
| TANK:   | - Septie Tank  | Holding Tank  | esspool Other: NA                            |                                |  |  |
| Tank Size: 500 Gal. 1000 Gal. Unknown Other: NA   |  |   |  |                                |  |  |
| Tank Ty   | <u></u>  | = =   | nknown Other: NA                             |                                |  |  |
| Location Location   | - —  |   | nknown Date of Installation: NA              |                                |  |  |
|   | st Pumped:   |   | ny Pumping Tank: NA                          |                                |  |  |
|   | u experienced any malfunction  |   |  | Yes No                         |  |  |
|   | ive the date and describe the  |   |  |                                |  |  |
| ), 8  |  |   |  |                                |  |  |
| Date of Last Servicing of tank:  Name of Company Servicing Tank: NA   |  |   |  |                                |  |  |
| LEACH FIELD: Yes No Unknown   |  |   |  |                                |  |  |
| #F YES: Location: NA  |  |   |  |                                |  |  |
| Date of installation of leach field: NA  Installed by: NA   |  |   |  |                                |  |  |
| Date of Last Servicing of leach field: NA  Name of Company Servicing leach field: NA  |  |   |  |                                |  |  |
| Have you experienced any malfunctions?  |  |   |  |                                |  |  |
| If yes, give the date and describe the problem & what steps were taken to remedy: NA  |  |   |  |                                |  |  |
|   |  |   |  |                                |  |  |
| Does Seller have records of the septic system design indicating the number of bedrooms the system was designed for?  Yes No |  |   |  |                                |  |  |
| IF YES, is it available? NA   |  |   |  |                                |  |  |
| Is System located in a Shoreland Zone? Yes No Unknown   |  |   |  |                                |  |  |
| Is System located in a Coastal Shoreland Zone? Yes No Unknown   |  |   |  |                                |  |  |
| COMMENTS: None  |  |   |  |                                |  |  |
| Source of SECTION II information: Seller  |  |   |  |                                |  |  |
| 2018 Page 1 of 3 - SPD Seller(s) Initials Buyer(s) Initials   |  |   |  |                                |  |  |
|   | Investment Realty, 72 Pine Street #16 Po   | rtland ME 04102   |  | x: 2077756688 Cumberland Flats |  |  |

PROPERTY LOCATED AT Cumberland Flats (Units 1-6), Portland, ME

| SECTION III. HEATING SYSTEM(S)/SOURCES(S)   |  |                                    |                             |                |  |  |  |
|---|--|------------------------------------|-----------------------------|----------------|--|--|--|
| Heating System(s)/Source(s)   | SYSTEM 1   | SYSTEM 2                           | SYSTEM 3                    | SYSTEM 4       |  |  |  |
| TYPE(S)   | Heat Pump/Elec                                     | Radiant/Elec                       | EcoSmart Firplc/Bio-ethenol |                |  |  |  |
| Age of system(s)/source(s)  | 2018 NEW/Builder                                   | 2018 NEW/Builder                   | 2018 NEW/Builder            |                |  |  |  |
| Name of company that services system(s)/source(s)   | NA   | NA                                 | NA                          |                |  |  |  |
| Date of most recent service call  | _20180511  | NA                                 | NA                          |                |  |  |  |
| Annual consumption per system/<br>source (i.e., gallons, kilowatt hours<br>cord(s))   | No Consumption records. New System                 | No Consumption records. New System | NA                          |                |  |  |  |
| Malfunction per system(s)/<br>source(s) within past 2 years   | NA   | NA                                 | NA                          |                |  |  |  |
| Other pertinent information   | None   | In Bathroom Floor                  | Ghost Model                 |                |  |  |  |
| •   |  |                                    | nknown Are all sleeved?     | Yes No Unknown |  |  |  |
| Chimney(s): Yes No If yes, lined: Yes No Unknown Last Cleaned: NA  Is more than one heat source vented through one flue? Yes No Unknown  Has chimney been inspected? Yes No Unknown; If Yes, when: NA  COMMENTS: All systems are new, never used  Source of SECTION III information: Seller |  |                                    |                             |                |  |  |  |
|   | SECTION IV   | HAZARDOUS MAT                      | TERIAL                      |                |  |  |  |
| The licensee is disclosing that the Seller is making representations contained herein.  A. UNDERGROUND STORAGE TANKS - Current or previously existing:  Are there now, or have there ever been, any underground storage tanks on your property?   |  |                                    |                             |                |  |  |  |
| Location: NA  |  |                                    |                             |                |  |  |  |
| Have you experienced any problems such as leakage? NA  Are tanks registered with the Dept. of Environmental Protection?   |  |                                    |                             |                |  |  |  |
| Source of information: Seller  A SRESTOS Current or previous  | iely exicting:                                     |                                    |                             |                |  |  |  |
| B. ASBESTOS - Current or previously existing:  • as insulation on the heating system pipes or duct work?  • in the siding?  |  |                                    |                             |                |  |  |  |
| Source of information: Seller  C PADON/AIP Current or prayi   | ough ovicting:                                     |                                    |                             |                |  |  |  |
| C. RADON/AIR - Current or previously existing:  Has the property been tested?   |  |                                    |                             |                |  |  |  |
|   | Has the property been tested since remedial steps? |                                    |                             |                |  |  |  |
| Are test results available? Yes X No Results & Comments: NA   |  |                                    |                             |                |  |  |  |
| Source of information: Seller  D. RADON/WATER - Current or previously existing: Has the property been tested?   |  |                                    |                             |                |  |  |  |
| Results: NA If applicable, What remedial steps were taken? NA   |  |                                    |                             |                |  |  |  |
| Has the property been tested since remedial steps?  |  |                                    |                             |                |  |  |  |
| E. LEAD-BASED PAINT/PAINT HAZARDS - Current or previously existing: (Note: Lead-based paint is most commonly found in homes constructed   |  |                                    |                             |                |  |  |  |
| prior to 1978) Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?  Yes X No Unknown Unknown but possible due to age  |  |                                    |                             |                |  |  |  |
| IF YES, describe location and the basis for the determination: NA  Do you know of any records or reports portaining to such load based point or load based point beyonds:  Ves. V. No.  |  |                                    |                             |                |  |  |  |
| Do you know of any records or reports pertaining to such lead-based paint or lead-based paint hazards: Yes X No IF YES, describe: NA  |  |                                    |                             |                |  |  |  |
| Are you aware of any cracking, peeling or flaking paint? Yes X No   |  |                                    |                             |                |  |  |  |
| Source of information: Seller/Builder   |  |                                    |                             |                |  |  |  |
| 2018 Page 2 of 3 - SPD Seller(s) Initials Buyer(s) Initials   |  |                                    |                             |                |  |  |  |

**Cumberland Flats** 

| PROPERTY LOCATED AT Cumberland Flats (Units 1-6), Portland  | I, ME  |
|---|--|
| F. OTHER HAZARDOUS MATERIALS - Current or previously exi  | isting:  |
| TOXIC MATERIAL: Yes No X Unknow   | -  |
| LAND FILL: Yes No X Unknow  |  |
| RADIOACTIVE MATERIAL: Yes No X Unknow   |  |
| Source of information: Seller   |  |
| Buyers are encouraged to seek information from professionals  | regarding any specific issue or concern.   |
| SECTION V. GEN  | ERAL INFORMATION   |
|   | sements, rights-of-way, leases, rights of first refusal, life estates, private way,                          |
| private road/homeowner associations (including condominiums and PU  |  |
| IF YES: Explain: HOA Documents & easements with 30 Merril   | ll Street  |
| Is access by means of a non-public way? Yes No X Unkr   | nown If YES, who is responsible for maintenance? NA  |
| What is your source of information: Seller/Deed/HOA Document  | ts   |
|   | on including but not limited to: Tree Growth, Open Space and Farmland,                                       |
| Veteran's, Homestead Exemption, Blind, Working Waterfront?  |  |
| <ul> <li>IF YES: Explain: NA Forest Ma</li> <li>Is this house currently covered by a flood insurance policy? (not a</li> </ul>  | nagement and Harvest Plan available?  Yes X No Unknown  determination of flood zone)                         |
| <ul> <li>Equipment leased or not owned (e.g., propane tank, hot water heat</li> </ul>   |  |
| <ul> <li>Year Principal Structure Built:</li> <li>2018</li> </ul>   | What year did Seller acquire property? <b>2016</b>   |
| Roof: Year Shingles/Other Installed: 2018   | What you and boiler dequire property.  |
| Water, moisture or leakage: NA  |  |
| Comments: None  |  |
| Foundation/Basement: Sump Pump: Yes X No Un   | known Comments: None   |
| • Water, moisture or leakage since you owned the property: Yes  | X No Unknown Comments: None  |
| Prior water, moisture or leakage? Yes   |  |
| • Mold: Has the property ever been tested for mold? Yes   |  |
| • Electrical: Fuses X Circuit Breaker Other:  |  |
| • Has all or a portion of the property been surveyed? X Yes   | No ☐ Unknown If YES, is the survey available? X Yes ☐ No Unknown Modular - ☐ Yes ☐ No X Unknown              |
|   | Unknown Modular - Yes No X Unknown Yor value of Property, including those that may have an adverse impact on |
| health/safety: None known   | alor value of Froperty, including those that may have an adverse impact on                                   |
| neartif sarety. 1 tone known  |  |
| Source of SECTION V information: Seller/Builder   |  |
| Seller shall be responsible and liable for any failure to provide known in  |  |
|   | REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN  |
| DISCLOSURE: Yes X No  |  |
| SECTION VI. ADDIT   | ΓΙΟΝΑL INFORMATION   |
| None  |  |
| Conc  |  |
|   |  |
|   |  |
| As Sellers, we have provided the above information and represent the  | nat all information is correct. To the best of our knowledge, all systems and                                |
| equipment, unless otherwise noted on this form, are in operational cond   |  |
|   |  |
| real Docusion of the control of the process of the safety, building but not limited to fire, life safety, building but not limited to fire the life safety life | cability of, or compliance with, any codes of any sort, whether state, municipal,                            |
| teneral of any other, including but not infinited to fire, the safety, building   | ng, electrical or plumbing. 5/11/2018  |
| 62DAD978CA88470 SELLER  | DATE   |
| — 62DAD978CA88470 SELLER  Five Seven, LLC   | DATE   |
| rive seven, LLC   |  |
| SELLER  | DATE   |
|   |  |
| I/We have read and received a copy of this disclosure, the arsenic in we<br>seek information from qualified professionals if I/we have questions or   | good fact sheet, the arsenic in water brochure, and understand that I/we should                              |
| seek information from quantieu professionals if t/we have questions of  | concerns.  |
| BUYER   | DATE   |
| <del>- v</del>  |  |
| DIMER   |  |
| BUYER   | DATE   |



 $\begin{tabular}{ll} \textbf{Maine Association of REALTORS@/Copyright @ 2018.} \\ \textbf{All Rights Reserved. Revised 2018.} \\ \end{tabular}$ 

Page 3 of 3 - SPD

